

U.S. ENVIRONMENTAL PROTECTION AGENCY  
POLLUTION/SITUATION REPORT  
Taylor Industrial Services - Removal Polrep

US EPA RECORDS CENTER REGION 5



456913



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Region V

**Subject:** POLREP #7  
Progress  
Taylor Industrial Services  
C5G6  
Mount Gilead, OH  
Latitude: 40.5508410 Longitude: -82.8550410

**To:** Valencia Darby, Department of Interior  
Kevin Clouse, Ohio EPA  
Sam Borries, U.S. EPA  
Mark Durno, U.S. EPA  
Jason El-Zein, U.S. EPA  
Sherry Fielding, U.S. EPA  
John Glover, U.S. EPA  
Randy Ohlemacher, Ohio EPA  
Dan Rogers, Village of Mount Gilead  
Thomas Marks, U.S. EPA  
Jeff Kelley, USEPA  
Tom Whiston, Morrow County  
Patricia Davies, Morrow County

**From:** Stephen Wolfe, On-Scene Coordinator

**Date:** 7/25/2013

**Reporting Period:** 07/08/13 through 07/26/13

## 1. Introduction

### 1.1 Background

Site Number:	C5G6	Contract Number:	
D.O. Number:		Action Memo Date:	9/19/2012
Response Authority:	CERCLA	Response Type:	Time-Critical
Response Lead:	EPA	Incident Category:	Removal Action
NPL Status:	Non NPL	Operable Unit:	
Mobilization Date:	4/8/2013	Start Date:	4/1/2013
Demob Date:		Completion Date:	
CERCLIS ID:		RCRIS ID:	
ERNS No.:		State Notification:	
FPN#:		Reimbursable Account #:	

#### 1.1.1 Incident Category

Abandoned Manufacturing Facility

#### 1.1.2 Site Description

See POLREP 1

##### 1.1.2.1 Location

The Site is located at 820 West Marion Road, Mt. Gilead, Morrow County, Ohio, 43338. The geographical coordinates for the Site are 40° 33' 10.64" North latitude and -82° 51' 17.27" West longitude. The Site where the release occurred is located in a mixed industrial, commercial and residential area.

The site is approximately 80 acres in size. Approximately 15 acres of the property is enclosed by a chain link fence and contains an approximate 300,000-square-foot building. Railroad tracks run along the northern portion of the property with a rail spur entering the fenced-in area. There is open farmland beyond the tracks. Residential properties are located approximately 0.1 miles to the east and west and a residential neighborhood borders the Site on the south on West Marion Road. A small creek flows around the fenced perimeter of the property and the creek eventually discharges to the Olentangy River.

##### 1.1.2.2 Description of Threat

See POLREP 1

#### 1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

See POLREP 1

## 2. Current Activities

### 2.1 Operations Section

#### 2.1.1 Narrative

During this reporting period, two loads of waste oil/water and three loads of petroleum contaminated

soil (low level pcbs) were transported off site for disposal. Other work including the following: the manufacturing pits were filled with on-site soils; RCRA empty containers were destroyed and placed in a roll-off box for removal; ERRS completed cleaning the pcb contaminated floors and preparing them for paint; ERRS began painting the pcb contaminated floors with epoxy paint.

### 2.1.2 Response Actions to Date

On July 8th, ERRS remobilized to the site from the July 4th Holiday.

During the week of July 8th, ERRS continued to clean the areas of the floors contaminated with pcbs. ERRS continued to fill in the machine pits with on site soils. Heavy rains throughout the week caused a buildup of rainwater in the unfilled pits due to holes in the roof of the building. ERRS consolidated the rainwater contaminated with waste oil, that entered the unfilled pits for removal.

During the week of July 15th, ERRS completed filling the machine pits with on site soils and completed cleaning the floors for paint preparation. On July 17th and 18th, 2 loads (11,000 gallons) of rainwater contaminated with waste oil were transported off site for disposal. Due to heavy rains floor painting was delayed.

During the week of July 22nd, ERRS mobilized turbo heaters to dry the pcb contaminated floor for painting. All RCRA empty containers were destroyed and placed in a roll-off box for disposal. On July 24th, ERRS began painting the first coat of epoxy paint on the pcb contaminated floor. On July 25th, 3 loads (60 yards) of petroleum contaminated soils (low level pcbs) were transported off site for disposal.

### 2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

The PRP has been identified and State and Federal enforcement activities are proceeding.

### 2.1.4 Progress Metrics

<i>Waste Stream</i>	<i>Medium</i>	<i>Quantity</i>	<i>Manifest #</i>	<i>Treatment</i>	<i>Disposal</i>
Corrossive, acid	liquid	8 drums	010006041JJK		Petro-Chem Processing Group, Detroit, MI
Corrossive, basic	liquid	17 drums	010006041JJK		Petro-Chem Processing Group, Detroit, MI
Flammable Liquid	liquid	12 drums	010006041JJK		Petro-Chem Processing Group, Detroit, MI
methylene chloride	liquid	600 gal	010006041JJK		Petro-Chem Processing Group, Detroit, MI
waste aerosols		1 drum	010006041JJK		Petro-Chem Processing Group, Detroit, MI
waste paint		3 drum	010006041JJK		Petro-Chem

					Processing Group, Detroit, MI
waste paint		5,000 lbs	010006041JJK		Petro-Chem Processing Group, Detroit, MI
non-haz waste oil/water	liquid	75,700 gal	001 - 014		Clean Water, Dayton Ohio
Acidic Liquid	liquid	4 drum	010006089JJK		Petro-Chem Processing Group, Detroit, MI
Grease		4 drum	010006089JJK		Petro-Chem Processing Group, Detroit, MI
Grease		2,000 lb	010006089JJK		Petro-Chem Processing Group, Detroit, MI
latex paint		1,000 lb	010006089JJK		Petro-Chem Processing Group, Detroit, MI
latex paint	sludge	41 drums	010006089JJK		Petro-Chem Processing Group, Detroit, MI
crushed bulbs		1 drum	010006089JJK		Petro-Chem Processing Group, Detroit, MI
oils	liquid	2 drum	010006089JJK		Petro-Chem Processing Group, Detroit, MI
PCB equipment		2 transformers 32 capacitors misc solid material and oil	004849395FLE 004849411FLE		Clean Harbors PPM LLC Twinsburg, Ohio
Low level pcb soil	soil	60 yards	1132607 1132608 1132609		Pine Grove Landfill Amanda, Ohio

## 2.2 Planning Section

### 2.2.1 Anticipated Activities

#### 2.2.1.1 Planned Response Activities

The following activities will take place at the site:

All containers will be consolidated inside the site building, staged and sampled for disposal.

All large pits containing waste oils will be sampled for disposal  
 All ASTs/USTs will be sampled for disposal  
 All chemicals will be disposed of at an US EPA approved disposal facility  
 All ASTs/USTs will be removed or rendered unusable  
 All pits containing waste oils will be cleaned and filled with site soil and rock.  
 Contaminated soil will be excavated and disposed.  
 Transformers will be investigated for PCB containing oil and disposed as appropriate.

#### 2.2.1.2 Next Steps

Complete filling of machine pits with rock

Complete painting pcb contaminated floor (two coats epoxy paint, white, then blue)

Dispose of pcb contaminated wood blocks

Dispose of RCRA empty containers/non-haz solid waste (approximately 20 tons)

#### 2.2.2 Issues

Heavy rains caused water buildup inside the building and machine pits. This delayed floor cleaning/painting and rainwater contaminated with waste oil was disposed.

#### 2.3 Logistics Section

no new information

#### 2.4 Finance Section

##### Estimated Costs \*

	Budgeted	Total To Date	Remaining	% Remaining
<b>Extramural Costs</b>				
ERRS - Cleanup Contractor	\$1,000,000.00	\$620,000.00	\$380,000.00	38.00%
TAT/START	\$75,000.00	\$60,000.00	\$15,000.00	20.00%
<b>Intramural Costs</b>				
USEPA - Direct	\$75,000.00	\$42,000.00	\$33,000.00	44.00%
<b>Total Site Costs</b>	<b>\$1,150,000.00</b>	<b>\$722,000.00</b>	<b>\$428,000.00</b>	<b>37.22%</b>

\* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

## **2.5 Other Command Staff**

### **2.5.1 Safety Officer**

A Health and Safety Plan was created for the site and all site workers have read and signed the plan.  
A daily Health and Safety meeting is held each day before the start of site work.

An emergency shower and eye wash has been set up outside the entrance to the building.

## **3. Participating Entities**

### **3.1 Unified Command**

### **3.2 Cooperating Agencies**

Ohio EPA  
Morrow County Prosecutor's Office  
Village of Mt. Gilead

## **4. Personnel On Site**

1 EPA OSC  
1 START - OTIE  
6 ERRS - Environmental Quality Management

## **5. Definition of Terms**

No information available at this time.

## **6. Additional sources of information**

No information available at this time.

## **7. Situational Reference Materials**

No information available at this time.